Nº 10177

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 2-5-92	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM			
HOUSE NO. 2340	7.116. W.11110EE 36111 G11.2.1112.2.2.2.2.2.2.2.2.2.2.2.2.2.2.2			
SIZE OF PIPE USED 6	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH			
WAS LATERAL AT CURB? 1/E_S				
WAS ATTACHED TO MAIN 15	NAME OF CONTRACTOR Betz Epc.			
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.				
	22° 7'05EP NA			
SIGNED Bill Panas Anispector for City	FILED AT ENGINEER'S OFFICE			
REMARKS	·			

№ 10177

OFFICE OF THE DIRECTOR OF PUBLIC SEI PERMIT TO TAP SEWER

	MASSILL	ON, OHIO,	<u> </u>
RECEIVED OF	<u> </u>	ang	
FOR WHICH PERMISSION IS GRANTED			
то тар	SEWER ON T	HE	
or 1/12/2/2/2/2/2/2/2/2/2/2/2/2/2/2/2/2/2/	AVE. ST. TYPE OF STI	REET	
THE PREMISES BEING LOT NO.	_		
WORK TO BE DONE IN ACCORDANCE WITH C	ORDINANCE NO. 19-19	71 DULY PASSED E	BY THE CITY COUNCIL, AND
OF THE DEPARTMENT OF PUBLIC SERVICE.			Ronovsky
NAME OF CONTRACTOR	ـــاــــــــــــــــــــــــــــــــــ		lonit

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.