Nº 10183

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 3-/7-92	IF SO HOW AND LOCATION FROM 122 DSM1 ON 27 155. 58.	
HOUSE NO. 309		
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH	
WAS LATERAL AT CURB? No	1944 - Carlo	
WAS ATTACHED TO MAIN 155	NAME OF CONTRACTOR Malarte Eye.	
SHOW BY DIAGRAM RELATION OF LATERAL TO WAL		
CIEAN OUT CAST THOM 98'=1. 78' 15'4' 15'4' 17'0EEP SIGNED Bill Panas	FILED AT ENGINEER'S OFFICE	
SIGNED SIGNED Inspector for City	THE RESIDENCE OF THE PROPERTY	
REMARKS House FACE'S Elizabeth Sw.		

Nº 10183

OFFICE OF THE DIRECTOR OF PUBLIC SEI PERMIT TO TAP SEWER

	MASSILLON, OHIO,
RECEIVED OF	# 6997/ FEE OF \$ 2
TO TAP	SEWER ON THE
OF AVI	E. TYPE OF STREET
THE PREMISES BEING LOT NO.	HOUSE NO. 369 Elizabeth
WORK TO BE DONE IN ACCORDANCE WITH ORDINANC OF THE DEPARTMENT OF PUBLIC SERVICE.	LIVER OF KUTAKELE.
NAME OF CONTRACTOR	

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.