Nº 10188

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 4-30-92	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM 126
HOUSE NO	
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH
WAS LATERAL AT CURB? 155	0
WAS ATTACHED TO MAIN LES	NAME OF CONTRACTOR Jerry Lyte
SHOW BY DIAGRAM RELATION OF LATERAL TO WAL	L OF BUILDING SERVED.
	7'+
	8'DEEP
	16-
0:10	6'DEEP
SIGNED BULL CAPPED	FILED AT ENGINEER'S OFFICE
Inspector for City	
DEMARKS	

ar

Nº 10188

OFFICE OF THE DIRECTOR OF PUBLIC SE PERMIT TO TAP SEWER

	MASSILLON, OHIO,	U 29
RECEIVED OF CLARATED		4.5
FOR WHICH PERMISSION IS GRANTED $\mathcal{L}\mathcal{A}$	in the second	
то тарs		mth
of Jamant ace SE AVE.		
THE PREMISES BEING LOT NO. 6248	, House no	1813
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE	NO. 19-1971 DULY PASSED BY THE	CITY COUNCIL, AND
OF THE DEPARTMENT OF PUBLIC SERVICE.	mpn Ger	vy Gar. 'unit
NAME OF CONTRACTOR ALLALA	1	unit
I		

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.