Nº 10198

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 6-24-92	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM			
HOUSE NO. 2572	. 3			
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH			
WAS LATERAL AT CURB?				
WAS ATTACHED TO MAIN YES	NAME OF CONTRACTOR Malivite Exc.			
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.				
	10/			
	S'CAST IFOH 7'L" DEEP			
SIGNED Bill Papped Inspector for City	9'DEEP FILED AT ENGINEER'S OFFICE			
DEMARKS				

tap № 10198

OFFICE OF THE DIRECTOR OF PUBLIC SE PERMIT TO TAP SEWER

en e	MASSILLO	ом, оню,	Me 18
RECEIVED OF AMILE	<u> Allelago</u>	ue et.	FEE OF \$\sqrt{5}(
FOR WHICH PERMISSION IS GRANTED			
то тар ДДП	SEWER ON TH	1E)(att.
TO TAP SAM	AVE ST. TYPE OF STR	EET	
THE PREMISES BEING LOT NO.			
WORK TO BE DONE IN ACCORDANCE WITH OF THE DEPARTMENT OF PUBLIC SERVICE.	RDINANCE NO. 19-197	1 DULY PASSED BY	THE CITY COUNCIL, AND
NAME OF CONTRACTOR TO THE CALLE	TL-E46		wit
		,	

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.