

N^o 10199

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 2-1-92

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

GOES out back of house

HOUSE NO. 817

SIZE OF PIPE USED —

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH


WAS LATERAL AT CURB? No

WAS ATTACHED TO MAIN YES

NAME OF CONTRACTOR

H & W Const.

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED

Bill Pappas
Inspector for City

FILED AT ENGINEER'S OFFICE

REMARKS

OFF

CUT OFF

Nº 10199

OFFICE OF THE DIRECTOR OF PUBLIC SE
PERMIT TO TAP SEWER

2

MASSILLON, OHIO, 6-25

RECEIVED OF

FIVE DOLLAR

FEE OF \$

5.00

FOR WHICH PERMISSION IS GRANTED

H & W Coaster

TO TAP

SEWTER

SEWER ON THE

WEST

OF

FRIE SD

AVE.

ST. TYPE OF STREET

ASPH

THE PREMISES BEING LOT NO.

9928

, HOUSE NO.

817

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19-1971 DULY PASSED BY THE CITY COUNCIL, AND
OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

H & W Coaster

**Note: This permit covers work outside of building only. Any work
walls of building is subject to Massillon Board of Health Regulations.**