

N^o 10201 FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 7-7-92 IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM 255'
HOUSE NO. 2542
SIZE OF PIPE USED 6" DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH _____
WAS LATERAL AT CURB? YES
WAS ATTACHED TO MAIN YES NAME OF CONTRACTOR Melvin Epc,
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED _____

Bill Pearson

Inspector for City

FILED AT ENGINEER'S OFFICE _____

REMARKS _____

tap
Nº 10201

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

MASSILLON, OHIO, July 1

RECEIVED OF Richard Murphy

FEE OF 50

FOR WHICH PERMISSION IS GRANTED Home

TO TAP San

SEWER ON THE 4th

OF Wilaflower Lane

AVE.
ST. TYPE OF STREET

THE PREMISES BEING LOT NO. 14678

HOUSE NO. 2542?
2542

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19-1971 DULY PASSED BY THE CITY COUNCIL, AND
OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Malavite Eng.

Richard Murphy
spec home
1 unit

**Note: This permit covers work outside of building only. Any work
walls of building is subject to Massillon Board of Health Regulations.**