## Nº 10219

## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 9-2-92	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM	
SIZE OF PIPE USED 6"  WAS LATERAL AT CURB? 465	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH	
WAS ATTACHED TO MAIN // SHOW BY DIAGRAM RELATION OF LATERAL TO WAL	NAME OF CONTRACTOR Los BUILDING SERVED.	
5'05°7		
vo/	10' Cast Iron Goss under porch	
SIGNED BILL PORPAS	7'40EFP FILED AT ENGINEER'S OFFICE	
// Inspectal for City		

## Nº 10219

## OFFICE OF THE DIRECTOR OF PUBLIC SEI PERMIT TO TAP SEWER

	MASSILLON, OHIO,
RECEIVED OF TIFTY DOLLARS	do FEE OF \$32
FOR WHICH PERMISSION IS GRANTED	EXCAU.
TO TAPSANTARYSE	WER ON THE
OF LAURI- TO SILL ST. TY	•
THE PREMISES BEING LOT NO	, HOUSE NO
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO	
NAME OF CONTRACTOR 7/5507 EXCAU	· Lunit

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.