Nº 10220

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 9-28-92	IF SO HOW AND LOCATION FROM 23
HOUSE NO. 108	
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH
WAS LATERAL AT CURB?	
	NAME OF CONTRACTOR Bushaya Wrecking
SHOW BY DIAGRAM RELATION OF LATERAL TO WAL	L OF BUILDING SERVED.
Federal And K. E	CURB 9th ST N.E.
SIGNED Bill approved inspector for City	FILED AT ENGINEER'S OFFICE

Nº 10220

OFFICE OF THE DIRECTOR OF PUBLIC SEI PERMIT TO TAP SEWER

	' .'		MASSILLON, OHIO			
•						
RECEIVED OF	£111	Alge.	<u>Unce</u>	KÌU	FEE OF \$_	
FOR WHICH PERMISSION	IS GRANTED		<u> </u>	···		
го т <u>а</u> р <u>(14.4.4.</u> ог	<u> </u>	AVE.	PE OF STREET		· -	
THE PREMISES BEING LO						
WORK TO BE DONE IN AC OF THE DEPARTMENT OF		,				
Note: This	Buck	I 1 7 6	tuck	Clox	Thirle	10
Note: This walls of building	permit cov g is subje	vers work ct to Mas	outside of b sillon Board	milding onl of Health	ly. Any wo	orl is.