

N^o 10221

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 9-24-92

IF SO HOW AND LOCATION FROM
FIRST MANHOLE ~~DOWN~~ STREAM

69'

HOUSE NO. 517

up

SIZE OF PIPE USED —

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH


WAS LATERAL AT CURB? YES

WAS ATTACHED TO MAIN YES

NAME OF CONTRACTOR E. Slick W. Needing

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

for



CURB AT TRIMONT S.E.

SIGNED Bill Pappas
Inspector for City

FILED AT ENGINEER'S OFFICE

REMARKS

Nº 10221

OFFICE OF THE DIRECTOR OF PUBLIC SEW

PERMIT TO TAP SEWER

MASSILLON, OHIO,

SEPT. 15th

RECEIVED OF

FIVE DOLLARS

FEE OF \$ 5

FOR WHICH PERMISSION IS GRANTED

ESLICH WRECKING

TO TAP

SANITARY

SEWER ON THE

SOUTH

OF

TREMONT AVE S.E.

AVE.

ST. TYPE OF STREET

ASPH

THE PREMISES BEING LOT NO.

9527

HOUSE NO.

517

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19-1971 DULY PASSED BY THE CITY COUNCIL, AND OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

ESLICH WRECKING CO

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.