Nº 10222

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED		IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM		,
HOUSE NO		DISTANCE FROM FIRST MANHOLE	-	
SIZE OF PIPE USED		DOWN STREAM TO DITCH AT CURB LINE AND DEPTH		
WAS LATERAL AT CURB?			•	
	GRAM RELATION OF LATERAL TO W	. NAME OF CONTRACTORALL OF BUILDING SERVED.	. <u></u>	
1				
	No Insp	ection	4.4 1	J.
SIGNED	Bill Popper	FILED A	T ENGINEER'S OFFICE	
	Inspector for Ci	ly .	- -	
DEMARDES				

Nº 10222

OFFICE OF THE DIRECTOR OF PUBLIC SEI PERMIT TO TAP SEWER

MASSILLON, OHIO, SEPT 15,1992				
RECEIVED OF FINE DOLLARS 00 FEE OF \$ 5.				
FOR WHICH PERMISSION IS GRANTED ESLICIT WRECKING CO.				
TO TAP SANTARY SEWER ON THE WEST				
OF ST. S.E. ST. TYPE OF STREET BRICK & ASPH				
THE PREMISES BEING LOT NO. 2822 , HOUSE NO. 417				
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19-1971 DULY PASSED BY THE CITY COUNCIL, AND OF THE DEPARTMENT OF FUBLIC SERVICE.				
FelmH Whermall				

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.

