

Nº 10227

**FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED**

DATE INSPECTED 11-17-92

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

HOUSE NO. 2110

SIZE OF PIPE USED 6"


DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

WAS LATERAL AT CURB? No

WAS ATTACHED TO MAIN YES

NAME OF CONTRACTOR

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



N 1

SIGNED

Bill Pappas
Inspector for City

FILED AT ENGINEER'S OFFICE

REMARKS

Dog Kennel is hooked into house lateral.

Nº 10227

OFFICE OF THE DIRECTOR OF PUBLIC SEI
PERMIT TO TAP SEWER

MASSILLON, OHIO, Oct 10

RECEIVED OF William H. E. Lee FEE OF \$ 50

FOR WHICH PERMISSION IS GRANTED

TO TAP SEWER ON THE

OF Danville Ave AVE.
ST. TYPE OF STREET

THE PREMISES BEING LOT NO. 01 555, HOUSE NO. 5110

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19-1971 DULY PASSED BY THE CITY COUNCIL, AND
OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Heldtbaum

**Note: This permit covers work outside of building only. Any work
walls of building is subject to Massillon Board of Health Regulations.**