N^{0} 10233

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 11-3-92 HOUSE NO. 2761	IF SO HOW AND LOCATION FROM 200 FIRST MANHOLE DOWN STREAM 200	
SIZE OF PIPE USED 6"	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH	
WAS LATERAL AT CURB? YE 5		
WAS ATTACHED TO MAIN_ 7E5	NAME OF CONTRACTOR Just Exter	
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.		
	20' \\ \[\frac{1}{20} \frac{5}{5} \pi \overline{\text{Fig}}	
	2 2 DEF P	
SIGNED BUILD aspects Inspector for City	FILED AT ENGINEER'S OFFICE	

راندار 10233 ≗

OFFICE OF THE DIRECTOR OF PUBLIC SEI PERMIT TO TAP SEWER

	MASSILLON, OHIO, Oct 23
RECEIVED OF LOSSO	ENC FEE OF \$50
FOR WHICH PERMISSION IS GRANTED.	ame
TO TAP SEI	
Abraham aren Works. TV	'PE OF STREET
THE PREMISES BEING LOT NO. 14637	
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO	
OF THE DEPARTMENT OF PUBLIC SERVICE.	Jessa Mai
NAME OF CONTRACTOR LOSS & Exa	

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.