Nº 10239

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 11-17- 92	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM				
HOUSE NO					
, //	DISTANCE FROM FIRST MANHOLE				
SIZE OF PIPE USED	DOWN STREAM TO DITCH AT CURB LINE AND DEPTH				
بر مر <i>با</i>	CORB LINE AND DEFIN				
WAS LATERAL AT CURB?					
WAS ATTACHED TO MAIN 185	NAME OF CONTRACTOR 26 oblesbours				
	·				
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.					
	- 450 Plastic				
	L'4"DEEP				
SIGNED Bill Garring	/ FILED AT ENGINEER'S OFFICE				
inspector for City					

REP AIR Nº 10239

OFFICE OF THE DIRECTOR OF PUBLIC SEI PERMIT TO TAP SEWER

RECEIVED OF	and	MASSILLON, OHIO,	<i>[101</i> _ %	1 /3 ₎ FEE OF \$2
FOR WHICH PERMISSION IS GRANTED		Q.A. 2016		
то тар. ДДД	sı	EWER ON THE		
of 164 H	AVE. ST. T	YPE OF STREET		
THE PREMISES BEING LOT NO	12103	, HOUSE	no/_7/	1-1
WORK TO BE DONE IN ACCORDANCE OF THE DEPARTMENT OF PUBLIC SEF	RVICE.			COUNCIL, AND
	Search Lander			

Note: This permit covers work outside of building only. Any work

walls of building is subject to Massillon Board of Health Regulations.