Nº 10246

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 12-2-92	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM GOES FATO MH	
HOUSE NO. 933		
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH	
WAS LATERAL AT CURB? 15		
WAS ATTACHED TO MAIN 45	NAME OF CONTRACTOR Liseat Eye	
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.		
	11'Z	
	125-	
SIGNED BUO Pappas	DEGO	
Inspector for City		
BENARKS		

Nº 10246 /AP

OFFICE OF THE DIRECTOR OF PUBLIC SEI PERMIT TO TAP SEWER

177	
RECEIVED OF FIFTY LOLLON	ASSILLON, OHIO, DEC 1
RECEIVED OF	The or quality
FOR WHICH PERMISSION IS GRANTED 115507	Excur.
TO TAP AUTERUS SEWE	
OF LAURI-JO: LANE SIE ST TYPE	OF STREET
THE PREMISES BEING LOT NO. 14248	, HOUSE NO833
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. OF THE DEPARTMENT OF PUBLIC SERVICE.	

NAME OF CONTRACTOR 11550T EXCHIV

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.