Nº 10253

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM	
HOUSE NO. 443	DISTANCE FROM FIRST MANHOLE	
WAS LATERAL AT CURB?	DOWN STREAM TO DITCH AT CURB LINE AND DEPTH	
WAS ATTACHED TO MAIN 7/2 5	NAME OF CONTRACTOR To olderbraum	
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.		
sety-	At house N 12121-1450 10 BILLDING SERVED. At house N 12121-1450 10 DEEP	
SIGNED BULL OF SIGNED Inspector for City	450 450 FILED AT ENGINEER'S OFFICE	

Nº 10253

OFFICE OF THE DIRECTOR OF PUBLIC SEI PERMIT TO TAP SEWER

	MASSILLON, OHIO, DEC 22
RECEIVED OF	DLLARS OU FEE OF \$ 5
FOR WHICH PERMISSION IS GRANTEDHC	OLDERE BUSY
TO TAP SANTARY	SEWER ON THE SOLDELL
OF	ST. TYPE OF STREET CHIP & SEAL
THE PREMISES BEING LOT NO. 13417	, House No. <u>443</u>
	DINANCE NO. 19-1971 DULY PASSED BY THE CITY COUNCIL, AND VELOPTICA KORNIOS
NAME OF CONTRACTOR FOLD GALBAD	m 1 unit

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.