Nº 10262

## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED /-20-53	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM  MH BN 2322 54.
HOUSE NO	
SIZE OF PIPE USED 6 Plastic	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH
WAS LATERAL AT CURB?	the state of the s
WAS ATTACHED TO MAIN 1/ES INTO MH	NAME OF CONTRACTOR Holdsborn Serve
SHOW BY DIAGRAM RELATION OF LATERAL TO WAL	L OF BUILDING SERVED. 24 5 NW.
	8'DEEP 2 20 At 228' From Mt
	8,000 by 4 228
	450
	23 nd N.W.
SIGNED Bill Pappar	mi 6'6"DEFD  FILED AT ENGINEER'S OFFICE
Inspector for City	

## OFFICE OF THE DIRECTOR OF PUBLIC SEI

## PERMIT TO TAP SEWER

MASSILLON, OHIO, (W) 12 28
RECEIVED OF HELDELLAND SEE OF \$ 5
FOR WHICH PERMISSION IS GRANTED
O TAP SEWER ON THE CALO
OF 24H (+) ( AVE. TYPE OF STREET
THE PREMISES BEING LOT NO. $3758 = 3757$ , House No. $32$
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19-1971 DULY PASSED BY THE CITY COUNCIL, AND DEF THE DEPARTMENT OF PUBLIC SERVICE.
NAME OF CONTRACTOR & AUGUSTALIAN

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.