

Nº 10275

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED _____

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM _____

HOUSE NO. _____

SIZE OF PIPE USED _____

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH _____

WAS LATERAL AT CURB? _____

WAS ATTACHED TO MAIN _____

NAME OF CONTRACTOR _____

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

NEVER FOUND IT. RUN NEW LINE FOR RALLEY'S

SIGNED _____

Bill Pappas
Inspector for City

FILED AT ENGINEER'S OFFICE _____

REMARKS _____

CUT OFF
No 10275

OFFICE OF THE DIRECTOR OF PUBLIC SEI
PERMIT TO TAP SEWER

MASSILLON, OHIO, 3-29

RECEIVED OF

FIVE DOLLARS 00

FEE OF \$ 5

FOR WHICH PERMISSION IS GRANTED

BUCKEYE WRECKING

CUT OFF
TO TAP

Sanitary

SEWER ON THE

North

OF

Lincoln Way East

AVE.

ST. TYPE OF STREET

ASPH

THE PREMISES BEING LOT NO.

487

HOUSE NO.

620

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19-1971 DULY PASSED BY THE CITY COUNCIL, AND
OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

BUCKEYE WRECKING

**Note: This permit covers work outside of building only. Any work
walls of building is subject to Massillon Board of Health Regulations.**