Nº 10276

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 8-9-93	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM
HOUSE NO. 2522	
SIZE OF PIPE USED 6	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH
WAS LATERAL AT CURB? 45	· · · · · · · · · · · · · · · · · · ·
WAS ATTACHED TO MAIN 155	NAME OF CONTRACTOR Malarito Efec
SHOW BY DIAGRAM RELATION OF LATERAL TO WAL	L OF BUILDING SERVED.
	14'7'DEGD NA
SIGNED Bill Pannon	8'6" DEF)
///inspector for City	
REMARKS	

Nº 10276

OFFICE OF THE DIRECTOR OF PUBLIC SEI PERMIT TO TAP SEWER

	MASSILLO	ON, OHIO,	<u></u>	<u> </u>	
RECEIVED OF	K.cha-	-phulp		FEE OF \$	æ.
FOR WHICH PERMISSION IS GRANTED	·				_
TO TAP	SEWER ON TH	1E	122		_
OF_1_1_ff	AVE, ST, TYPE OF STR	EET			
THE PREMISES BEING LOT NO. 14676	<u>r</u>	, HOUSE NO	752	2	_
WORK TO BE DONE IN ACCORDANCE WITH ORDI	INANCE NO. 19-197	1 DULY PASSED B	Y THE CITY	COUNCIL, AND)
OF THE DEPARTMENT OF PUBLIC SERVICE.		Jo mes	6.61	سسرره و	
NAME OF CONTRACTOR					

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.