## Nº 10311

## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 2-14-93	IF SO HOW AND LOCATION FROM 256				
HOUSE NO					
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH				
WAS LATERAL AT CURB?					
WAS ATTACHED TO MAIN VES	NAME OF CONTRACTOR Bill Souris				
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.					
200 P	30° 8'DEEP NA				
SIGNED BILL GARAGE	FILED AT ENGINEER'S OFFICE				
ljíspector for City					

Nº 10311

OFFICE OF THE DIRECTOR OF PUBLIC SEI

PERMIT TO TAP SEWER

-	-) <i>y</i>			
		MASSILLON, OHIO,	<u>J. 4</u>	15
RECEIVED OF	Um D.L	ens		FEE OF \$
FOR WHICH PERMISSION IS G	GRANTED			
TO TAP	si	EWER ON THE	Nocte	· · · · · · · · · · · · · · · · · · ·
OF 5/10-1	AVE. AVE. T. T	YPE OF STREET		
THE PREMISES BEING LOT N				
WORK TO BE DONE IN ACCORD	RDANCE WITH ORDINANCE N BLIC SERVICE.	10. 19-1971 DULY PAS MRS	Bernic.	COUNCIL, AND
WORK TO BE DONE IN ACCORD  THE DEPARTMENT OF PUI  NAME OF CONTRACTOR	War Dites	101	217	c , c 7

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.