

Nº 10313

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 8-5-93

IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM 183'

HOUSE NO. 1224

SIZE OF PIPE USED 6"


DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH

WAS LATERAL AT CURB? No

WAS ATTACHED TO MAIN YES

NAME OF CONTRACTOR J. Gluck

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



N4

SIGNED Bill Pappas
Inspector for City

FILED AT ENGINEER'S OFFICE

REMARKS

10p
N^o 10313

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

MASSILLON, OHIO, July 20

RECEIVED OF

Jacob Glick

FEE OF \$ 5.00

FOR WHICH PERMISSION IS GRANTED same

TO TAP San

SEWER ON THE N

OF Woodruff Ave NW

AVE.

ST. TYPE OF STREET

THE PREMISES BEING LOT NO. 4894

HOUSE NO. 1724

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19-1971 DULY PASSED BY THE CITY COUNCIL, AND
OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Glick

m/m Joseph K
unit

**Note: This permit covers work outside of building only. Any work
walls of building is subject to Massillon Board of Health Regulations.**