N^{0} 10314

8-5-97

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED	FIRST MANHOLE DOWN STREAM GOES INTO MH
HOUSE NO. 836-834	
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH
WAS LATERAL AT CURB?	Lint Etc.
was attached to main_\(\frac{\frac{1}{2}}{2} \)	NAME OF CONTRACTOR JUSTICAL STATE OF CONTRACTOR
SHOW BY DIAGRAM RELATION OF LATERAL TO WAL	L OF BUILDING SERVED. (7) md
	NAME OF CONTRACTOR L OF BUILDING SERVED. 20 33 22'' 20'' 33' 22'' 20'' 220''
	220 33 (22" SET 4
• .	220
	$\frac{33}{30}$
	7'056
- -	DRITZ
BIMP COM	FILTE AT PROMETRIE OFFICE
SIGNED BU Tapped Inspector for City	FILED AT ENGINEER'S OFFICE
a 1	
H = 0	

Nº 10314

OFFICE OF THE DIRECTOR OF PUBLIC SEI PERMIT TO TAP SEWER

	MASSILLON, OHIO,
RECEIVED OF XIII	777 169 FEE OF \$50
OR WHICH PERMISSION IS GRANTED	1
OF ALLES CAVE.	TYPE OF STREET
THE PREMISES BEING LOT NO. 1424. T	, HOUSE NO. 834+830
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE OF THE DEPARTMENT OF PUBLIC SERVICE,	NO. 19-1971 DULY PASSED BY THE CITY COUNCIL, AND
NAME OF CONTRACTOR	Zunits

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.