

N^o 10315

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 7-22-93

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

169'

HOUSE NO. 2571

SIZE OF PIPE USED 6"

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH


WAS LATERAL AT CURB? YES

WAS ATTACHED TO MAIN YES

NAME OF CONTRACTOR

Malowide Eng.

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED

Inspector for City

FILED AT ENGINEER'S OFFICE

REMARKS

Nº 10315 *dup*

OFFICE OF THE DIRECTOR OF PUBLIC SE

PERMIT TO TAP SEWER

MASSILLON, OHIO, *July 23*

RECEIVED OF *H & W*

FEE OF \$ *50*

FOR WHICH PERMISSION IS GRANTED *None*

TO TAP *Jefferson*

SEWER ON THE *S*

OF *Tribble Creek Circle*

AVE.

ST. TYPE OF STREET

THE PREMISES BEING LOT NO. *14864*

HOUSE NO. *2571*

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19-1971 DULY PASSED BY THE CITY COUNCIL, AND OF THE DEPARTMENT OF PUBLIC SERVICE. *Copy same*

NAME OF CONTRACTOR *H & W*

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.