Nº 10318

## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM
HOUSE NO	
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH
WAS LATERAL AT CURB?	and the second of the second o
WAS ATTACHED TO MAIN	NAME OF CONTRACTOR
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL	
	16 July 20 19 19 19 19 19 19 19 19 19 19 19 19 19
SIGNED	FILED AT ENGINEER'S OFFICE
Inspector for City	FILED AT ENGINEER'S OFFICE
REMARKS	·

atoff

## OFFICE OF THE DIRECTOR OF PUBLIC SE PERMIT TO TAP SEWER

	MASSILLON, OHIO, (1/1/2/2/6)
RECEIVED OF	100 110 100 FEE OF \$
OR WHICH PERMISSION IS GRANTED	
TO TAPULE TO A SULTE	SEWER ON THE
-10t (1710ct . S	AVE.
THE PREMISES BEING LOT NO.210	# 2// 381/ # 2// , HOUSE NO. 5/ 4 5- 0 + 06 - 1445 Z RDINANCE NO. 19-1971 DULY PASSED BY THE CITY COUNCIL, AND
NORK TO BE DONE IN ACCORDANCE WITH OR	O + 06-14452 RDINANCE NO. 19-1971 DULY PASSED BY THE CITY COUNCIL, AND
NAME OF CONTRACTOR	City of 41 Tavous
NAME OF CONTRACTOR	

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.