Nº 10322

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 9-3-93 HOUSE NO. 2835	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM 10.5
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH
WAS LATERAL AT CURB? 155 WAS ATTACHED TO MAIN 155 SHOW BY DIAGRAM RELATION OF LATERAL TO WA	NAME OF CONTRACTOR & Licks
SHOW BY DIAGRAM RELATION OF LATERAL TO WA	LE OF BOTESING SERVES.
	25 P 6'of 4"
数据	8 pet) 6 of 4"
	70597
SIGNED Bill Pany Inspector for City	FILED AT ENGINEER'S OFFICE
REMARKS	

√ 10322 ⁷

OFFICE OF THE DIRECTOR OF PUBLIC SEI PERMIT TO TAP SEWER

RECEIVED OF		LLON, OHIO, (1)	
FOR WHICH PERMISSION IS GRANTED	11446		
TO TAP	sewer on	THE	5
DF 466-4464-1266-	AVE. ST. TYPE OF S	TREET	*
THE PREMISES BEING LOT NO. 148			<u> </u>
WORK TO BE DONE IN ACCORDANCE WITH O	Section 29 of	DULY PASSED BY	THE CITY COUNCIL, AND
OF THE DEPARTMENT OF PUBLIC SERVICE.	Y	arnec	i Keun Ghe
NAME OF CONTRACTOR	VIlleds		lunit
\mathcal{F}			

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.