## $N^{0}$ 10333

## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 9-27-93 HOUSE NO. 1420	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM  125	
SIZE OF PIPE USED 6 17  WAS LATERAL AT CURB? 7 5	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH	
WAS ATTACHED TO MAIN	NAME OF CONTRACTOR But Effe	
SIGNED BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.  1		
//		

Nº 10333

## OFFICE OF THE DIRECTOR OF PUBLIC SEI PERMIT TO TAP SEWER

•	MASSILLON, OHIO,	<u>. Uga 22 </u>
RECEIVED OF		FEE OF \$50
OR WHICH PERMISSION IS GRANTED	144714	
O TAP	SEWER ON THE	9901tl
FRAUL CLETTE	AVE.	
HE PREMISES BEING LOT NO. 14	483 , HOU	se no. 1420
ORK TO BE DONE IN ACCORDANCE WITH (	Section 29 of Cod- DULY	
IAME OF CONTRACTOR 1	F 12 F1	- 1 66764
Note: This permit cover		

walls of building is subject to Massillon Board of Health Regulations.