Nº 10334

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

	DATE INSPECTED	10-5-93	IF SO HOW AND LOCATION FIRST MANHOLE DOWN ST			
	HOUSE NO		DISTANCE FROM FIRST MA DOWN STREAM TO DITCH A CURB LINE AND DEPTH		94' downstream	MH to wye
	WAS LATERAL AT C	urb? <u>Ves</u>	200		.00	
;	WAS ATTACHED TO	MAIN YES	NAME OF CONTRACTOR	Malavite	Exc.	
	show by diagram 11 south ty line	tie in-8' deep / 2' @tie in 31" piece 6	in from street 29	1' from so	4th property line	7 - 22½° E160W
enters unde		45° Elbow 7' piece 6" plastic 3-10' sections 6" plast			tie in	- 45° EI BOW CURB
of	front porch	6'10" piece 6" plastie 22'2" Elbow-6" 5'piece 6" plastic /6	6"to 4"furneo/ 7°4	•	95 plastic use -	wye q4'
. *	SIGNED ACTION ///	Inspector for City	,FI	LED AT ENGI	NEER'S OFFICE	

№ 10334 ^{///}/

OFFICE OF THE DIRECTOR OF PUBLIC SEI PERMIT TO TAP SEWER

MASSILLON, OHIO,			
Devil	4 1/1/2010		
SEWE	R ON THE $\frac{244}{1}$	<u> </u>	
AVE.	OF STREET		
111	House No	1320	
Section 29 of ified Ordina	of Cod- DULY PASSED B ances M/M //M	THE CITY COUNCIL, AND WAS AND WITH	
	Section 29 of iffied Ordina	SEWER ON THE SEWER ON THE AVE. TYPE OF STREET HOUSE NO. Section 29 of Cod- ified Ordinances M/M M/M M/M M/M M/M M/M M/M M	

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.