Nº 10366 FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 7-7-94	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM	
HOUSE NO. 1741	,	
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH	
WAS LATERAL AT CURB?		
WAS ATTACHED TO MAIN YES	NAME OF CONTRACTOR TELSO EFC	
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.		
	7'4 3' DEEP 7'4 3' DEEP 450	
SIGNED Bill Carnes	0-22°7'DEE/P	
SIGNED Inspector for City	FILED AT ENGINEER'S OFFICE	
BEMARKS GOES TITO MH IN BACK WARD OF 1319 Providice N. E.		

taf 10366

OFFICE OF THE DIRECTOR OF PUBLIC SE PERMIT TO TAP SEWER

	MASSILLON, OHIO, MARCH
RECEIVED OF	TISSOTEXC FEE OF \$ 50
FOR WHICH PERMISSION IS GRANTED	
	EWER ON THE
OF WALES ROUNE AVE.	TYPE OF STREET
THE PREMISES BEING LOT NO. 8763	, HOUSE NO
WORK TO BE DONE IN ACCORDANCE WITH (Section of the department of public service. Codified (NAME OF CONTRACTOR ILSSOT	Drdinances Ralph Rottona Co. Lunit

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.