$N^{0} = 10368$

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 3-3-94	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM
SIZE OF PIPE USED 6" WAS LATERAL AT CURB? YES	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH
	NAME OF CONTRACTOR TISSOT 18' tie in to carb
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL	22'2° Elbow @ tic in- 17' of 6" plastic 22'2° Elbow @ tic in- 17' of 6" plastic 22'2° Elbow 6" 13'2" of 6" plastic 22'2° atie in 6" to 4" (colucer @ house 7' deep@house 18'8" South corner of house to & 6
SIGNED Doug Millor Inspector for City	18'8" FILED AT ENGINEER'S OFFICE
REMARKS	

+αρ 10368

OFFICE OF THE DIRECTOR OF PUBLIC SEI PERMIT TO TAP SEWER

MASSILLON, OHIO, March 2-1
RECEIVED OF MAY JOHN FEE OF \$ 5
or which permission is granted
O TAPSEWER ON THE WEST
F POPLUS QUE NW ST. TYPE OF STREET
HE PREMISES BEING LOT NO. 14825 , HOUSE NO. 282/
ORK TO BE DONE IN ACCORDANCE WITH Codified Ordinances ULY PASSED BY THE CITY COUNCIL, AND
F THE DEPARTMENT OF PUBLIC SERVICE. COOTTING OF OTHER CONTRACTOR TISSET EXC.
IAME OF CONTRACTOR 7/30/1 CXC.

Note: This permit covers work outside of building only. Any worl walls of building is subject to Massillon Board of Health Regulations.