

Nº 10373

**FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED**

DATE INSPECTED 7-21-94

IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM 94' to downstream MH

HOUSE NO. 1310

SIZE OF PIPE USED 6"

DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH _____


WAS LATERAL AT CURB? yes

WAS ATTACHED TO MAIN yes

NAME OF CONTRACTOR Tissot

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

10' deep @ tie in,
then 45° & 22½° Elbows @ tie in
4' piece 6" plastic,
45° Elbow,
19' section of 6" plastic,
45° & 22½° Elbows,
40" piece 6" plastic,
furnco fitting 6" to 4"



{ 16' from NW corner of house
to line into foundation
{ 2' out from
foundation
4" to 6" furnco fitting
attached, 7' deep

SIGNED _____
Inspector for City

FILED AT ENGINEER'S OFFICE _____

REMARKS _____

Nº 10373

Tap

OFFICE OF THE DIRECTOR OF PUBLIC SE

PERMIT TO TAP SEWER

MASSILLON, OHIO,

April 7/11

RECEIVED OF

RETURN

FEE OF \$

5

FOR WHICH PERMISSION IS GRANTED

TO TAP

Sanitary

SEWER ON THE

South

OF

Beech Tree

NE

AVE.
ST.

TYPE OF STREET

THE PREMISES BEING LOT NO.

144916

HOUSE NO.

1310

WORK TO BE DONE IN ACCORDANCE WITH
OF THE DEPARTMENT OF PUBLIC SERVICE.

Section 29
Codified Ordinances

DULY PASSED BY THE CITY COUNCIL, AND

owner.

NAME OF CONTRACTOR

T. S. SOT

Ms Camille Leslie
1 unit

Note: This permit covers work outside of building only. Any work
walls of building is subject to Massillon Board of Health Regulations.