Nº 10381

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 4-26-94	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM	
HOUSE NO	DISTANCE FROM FIRST MANHOLE	
SIZE OF PIPE USED	DOWN STREAM TO DITCH AT CURB LINE AND DEPTH	
WAS LATERAL AT CURB?		
WAS ATTACHED TO MAIN	NAME OF CONTRACTOR	
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.		
Line Changed going through parking lot		
10500		
SIGNED 73 U Confidence of the Inspector for City	FILED AT ENGINEER'S OFFICE	
•		
REMARKS		

Nº 10381

OFFICE OF THE DIRECTOR OF PUBLIC SEI PERMIT TO TAP SEWER

	MASSILLON, OHIO, 19	ri/25
RECEIVED OF	g. Pizzo	FEE OF \$_\
TO TAP	SEWER ON THE	Ast
OF	AVE.	
THE PREMISES BEING LOT NO.	<u> 0 5 3 0</u> , HOUSE NO	<u> </u>
WORK TO BE DONE IN ACCORDANCE WITH OF THE DEPARTMENT OF PUBLIC SERVICE	ORDINANCE NO. 19-1971 DULY PASSED B	Y THE CITY COUNCIL, AND
NAME OF CONTRACTOR	(

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.

