N^{0} 10386

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 8-9-94	IF SO HOW AND LOCATION FROM 93 DS MH	
HOUSE NO. 806	,	
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH	
WAS LATERAL AT CURB?/E_S		
WAS ATTACHED TO MAIN 725	NAME OF CONTRACTOR J. Like	
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.		
From 30' S'DEEP GARAGE 6' OFFP		
SIGNED Bill Pages Inspector for City	FILED AT ENGINEER'S OFFICE	
	Existing 4" line	

Nº 10386 tap

OFFICE OF THE DIRECTOR OF PUBLIC SEI PERMIT TO TAP SEWER

•		
	MASSILLON, OHIO,	13
RECEIVED OF	great Which	
OR WHICH PERMISSION IS GRANTED	<u>JANU</u>	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,
D TAP	SEWER ON THE	12.X
. 94× Ut S/C)		
	<u>4.32/3</u> , HOUSE NO	804
	Section 29 Codified Ordinances DULY PASSED BY THE	
F THE DEPARTMENT OF PUBLIC SERVICE.	OAnb	Glick
AME OF CONTRACTOR		mit

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.