

N^o 10396

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 8-1-94

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

GOES AROUND CORNER

HOUSE NO. 103

SIZE OF PIPE USED -

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH


WAS LATERAL AT CURB? YES

WAS ATTACHED TO MAIN YES

NAME OF CONTRACTOR

Cottrell Wrecking

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED

Bill Rogers
Inspector for City

FILED AT ENGINEER'S OFFICE

REMARKS

Cutoff
Nº 10396

OFFICE OF THE DIRECTOR OF PUBLIC SEWERS
PERMIT TO TAP SEWER

MASSILLON, OHIO, *July 27*

RECEIVED OF *William H. H. H. H.*

FEE OF \$ *1*

FOR WHICH PERMISSION IS GRANTED *same*

TO TAP *Cutoff*

SEWER ON THE

OF *Road line SE*

AVE.
ST. TYPE OF STREET

THE PREMISES BEING LOT NO. *1448*

HOUSE NO. *203*

WORK TO BE DONE IN ACCORDANCE WITH
OF THE DEPARTMENT OF PUBLIC SERVICE.

Section 29
Codified Ordinances

DULY PASSED BY THE CITY COUNCIL, AND

NAME OF CONTRACTOR *William H. H. H. H.*

**Note: This permit covers work outside of building only. Any work
walls of building is subject to Massillon Board of Health Regulations.**