

N^o 10409

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 9-16-94

IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM GOES INTO 1/2 SET OUTSIDE OF M.

HOUSE NO. 155

SIZE OF PIPE USED 6"


DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH _____

WAS LATERAL AT CURB? No

WAS ATTACHED TO MAIN YES

NAME OF CONTRACTOR H & W Contractors

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



N 4

SIGNED Bill Pappas
Inspector for City

FILED AT ENGINEER'S OFFICE _____

REMARKS _____

7-17-20
Nº 10409

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

MASSILLON, OHIO, May 16,

RECEIVED OF

H. W. Continetta FEE OF \$ 50

FOR WHICH PERMISSION IS GRANTED

TO TAP

San SEWER ON THE North

OF

Lincoln Way West AVE.
ST. TYPE OF STREET

THE PREMISES BEING LOT NO.

P4 01 700 HOUSE NO. 155

WORK TO BE DONE IN ACCORDANCE WITH
OF THE DEPARTMENT OF PUBLIC SERVICE.

Section 29
Codified Ordinances

DULY PASSED BY THE CITY COUNCIL, AND

NAME OF CONTRACTOR

H. W. Continetta Darrell Develop
1 Bldg.

Note: This permit covers work outside of building only. Any work
walls of building is subject to Massillon Board of Health Regulations.