Nº 10413

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM	
HOUSE NO. 2725		
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH	
WAS LATERAL AT CURB? 455		
WAS ATTACHED TO MAIN 755	NAME OF CONTRACTOR Holdstraum	
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.		
5.2	718'8" T 4'4"PiPe 8'0EEP 7'6" 7450	
SIGNED BILD Papper SIGNED BILD Papper Inspector for City FILED AT ENGINEER'S OFFICE		
REMARKS		

Nº 10413

OFFICE OF THE DIRECTOR OF PUBLIC SEI PERMIT TO TAP SEWER

	MASSILLON, OHIO, Dept 2	
RECEIVED OF	py the lice of \$50	
FOR WHICH PERMISSION IS GRANTED	N.	
TO TAP SE	WER ON THE	
OF Chausey Ave ST. TY	'PE OF STREET	
THE BREMISES BEING LOT NO 1.3 420 - 2:	Z HOUSE NO. 2725	
WORK TO BE DONE IN ACCORDANCE WITH C Section 29 OF THE DEPARTMENT OF PUBLIC SERVICE. Codified Ordinances		
NAME OF CONTRACTOR	<u>. dell</u>	

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.

Manuel Morales