## Nº 10417

## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

| DATE INSPECTED 10-13-94                    | IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM                   |
|--|---|
| HOUSE NO. 84/                              |   |
| SIZE OF PIPE USED                          | DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH |
| WAS LATERAL AT CURB?                       |   |
| WAS ATTACHED TO MAIN 75                    | NAME OF CONTRACTOR Cathell  |
| SHOW BY DIAGRAM RELATION OF LATERAL TO WAL |   |
| 9 2575 We UR                               | 74' 546" NoteP  |
| SIGNED BELL CARDEST Inspector for City     | FILED AT ENGINEER'S OFFICE  |
| REMARKS                                    |   |

## Nº 10417 OFFICE OF THE DIRECTOR OF PUBLIC SE

|  |                | MASSILLON,           | оню,          |          | 1:4              |
|--|----------------|----------------------|---------------|----------|------------------|
| RECEIVED OF  | <u> (15</u>    |                      |               | <u> </u> | FEE OF \$        |
| OR WHICH PERMISSION IS GRANTED   |                | ( m                  |               |          | ·                |
| OTAF (1.17)  | AVE            | SEWER ON THE.        | • <del></del> |          | <del></del>      |
| HE PREMISES BEING LOT NO.  |                |                      |               |          | 27/              |
| VORK TO BE DONE IN ACCORDANCE WITH CONFITTED THE DEPARTMENT OF PUBLIC SERVICE. | Sect<br>dified | ion 29<br>Ordinances | DULY PASSED   | BY THE C | ITY COUNCIL, AND |

Note: This permit covers work outside of building only. Any worl walls of building is subject to Massillon Board of Health Regulations.