Nº 10418

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM
HOUSE NO. 20-29-35	
SIZE OF PIPE USED 6"	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH
WAS LATERAL AT CURB?	
WAS ATTACHED TO MAIN 4E5	NAME OF CONTRACTOR Bob Schaen
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.	
Clearly of	10'4" PN
SIGNED Bill Parpus	6 DEF P FILED AT ENGINEER'S OFFICE
Inspector for City	

-18

Nº 10418

DET. 13, 1984

OFFICE OF THE DIRECTOR OF PUBLIC SE PERMIT TO TAP SEWER

MASSILLON, OHIO, Ut. 13
RECEIVED OF Robert Schaer, gr. FEE OF S.
No me
FOR WHICH PERMISSION IS GRANTED.
TO TAP SEWER ON THE
Lmcolo Why E. AVE.
2029, 2031, THE PREMISES BEING LOT NO. 6/1/1 , HOUSE NO. 2033, 2035
WORK TO BE DONE IN ACCORDANCE WITH Coclified Ordinarices Duly passed by the city council, and
OF THE DEPARTMENT OF PUBLIC SERVICE.
NAME OF CONTRACTOR SCHOOL HOLD TO
Note: This powers covery would outside of building only. Any world

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.