Nº 10432

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 5-15-95	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM6_9		
HOUSE NO. 2/7	•		
SIZE OF PIPE USED 4 7	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH		
WAS LATERAL AT CURB? // S	A		
WAS ATTACHED TO MAIN 16.5	NAME OF CONTRACTOR & alderteum		
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.			
	17'		
SIGNED Bill Pansas	g'OFF		
<i>V V</i>			

Nº 10432

OFFICE OF THE DIRECTOR OF PUBLIC SEI PERMIT TO TAP SEWER

dra .	MASSIL	LON, OHIO, ()/1/1/2	<u>9</u>
RECEIVED OF	tolders	auril.	FEE OF \$.54
OR WHICH PERMISSION IS GRANTED	<u> </u>		
O TAP	SEWER ON	тне	/ -{}
F. 20 4 St 57			
HE PREMISES BEING LOT NO. 1398	<u> + 99 </u>	, HOUSE NO/	7
F THE DEPARTMENT OF PUBLIC SERVICE. COD	Section 29 ified Ordinanc	es DULY PASSED BY THE CI	ty council, and K Calle
IAME OF CONTRACTOR	2-72LL(-11-1	100	nut

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.