

Nº 10437

**FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED**

DATE INSPECTED 1-19-95

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM 98'

HOUSE NO. 12

SIZE OF PIPE USED 4"



DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

WAS LATERAL AT CURB? No

WAS ATTACHED TO MAIN YES

NAME OF CONTRACTOR Holdabaum

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED Bill Pappas

Inspector for City

FILED AT ENGINEER'S OFFICE

REMARKS was hooked into septic tank.

Nº 10437

OFFICE OF THE DIRECTOR OF PUBLIC SE
PERMIT TO TAP SEWER

MASSILLON, OHIO, Jan 20

RECEIVED OF Lesly H. Hildebrand

FEE OF \$ 50

✓ FOR WHICH PERMISSION IS GRANTED _____

TO TAP Ref. 1

SEWER ON THE N. Main

OF Flange

AVE.

ST. TYPE OF STREET _____

THE PREMISES BEING LOT NO. 2563

HOUSE NO. 13

WORK TO BE DONE IN ACCORDANCE WITH
OF THE DEPARTMENT OF PUBLIC SERVICE.

Section 29
Codified Ordinances

DULY PASSED BY THE CITY COUNCIL, AND

m NAME OF CONTRACTOR Lesly H. Hildebrand

**Note: This permit covers work outside of building only. Any work
walls of building is subject to Massillon Board of Health Regulations.**