Nº 10443

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 3-13-95	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM
HOUSE NO. 909	
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH
WAS LATERAL AT CURB? 45	_
WAS ATTACHED TO MAIN 45	NAME OF CONTRACTOR AT Diane
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL	
REPAIR	
JN SAME	REPAIR 8'
	L'DEEP
SIGNED Bill Passon	FILED AT ENGINEER'S OFFICE
REMARKS	·

Nº 10443

OFFICE OF THE DIRECTOR OF PUBLIC SE

	MASSILLON, OHIO,	題/3
RECEIVED OF	IJ Quan Sono	
FOR WHICH PERMISSION IS GRANTED	<u>LOMANC</u>	
го тар	SEWER ON THE	<u> </u>
	AVE.	
	, HOUSE NO	
WORK TO BE DONE IN ACCORDANCE WITH OF THE DEPARTMENT OF PUBLIC SERVICE.	Section 29 DULY PASSED BY TH	łĖ CITY COUNCIL, AND
NAME OF CONTRACTOR		

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.