

N^o 10457

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 5-8-95

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

GOES INTO MH

HOUSE NO. 300

SIZE OF PIPE USED -

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH


WAS LATERAL AT CURB? YES

WAS ATTACHED TO MAIN YES

NAME OF CONTRACTOR

Cottrell Wrecking

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED _____

Inspector for City

FILED AT ENGINEER'S OFFICE

REMARKS _____

Cutoff
N^o 10457

OFFICE OF THE DIRECTOR OF PUBLIC SE
PERMIT TO TAP SEWER

MASSILLON, OHIO, MAY 8

RECEIVED OF CENTRAL REPAIRATION FEE OF \$ 0

FOR WHICH PERMISSION IS GRANTED CUT OFF SEWER

TO TAP SEWER ON THE NORTH

OF LINCOLN WAY W AVE.
ST. TYPE OF STREET

THE PREMISES BEING LOT NO. 401-406, HOUSE NO. 300

WORK TO BE DONE IN ACCORDANCE WITH Section 29
OF THE DEPARTMENT OF PUBLIC SERVICE. Codified Ordinances DULY PASSED BY THE CITY COUNCIL, AND

NAME OF CONTRACTOR CENTRAL City
unit

**Note: This permit covers work outside of building only. Any work
walls of building is subject to Massillon Board of Health Regulations.**