Nº 10458

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 5/23/95	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM
HOUSE NO. 2340	
SIZE OF PIPE USED 6" plastic	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH
WAS LATERAL AT CURB?	Qual-
WAS ATTACHED TO MAIN	NAME OF CONTRACTOR BUTTOCEY
SHOW BY DIAGRAM RELATION OF LATERAL TO WALI	LOF BUILDING SERVED
	5/23/95 0/d
	220
1 m Cuo	FILED AT ENGINEER'S OFFICE
SIGNED Inspector for City	
REMARKS FOURCOTICN NOT YELL CX	canaled

//// № 10458

OFFICE OF THE DIRECTOR OF PUBLIC SEI PERMIT TO TAP SEWER

	MASSILLON, OHIO,	1) (14 18)
RECEIVED OF	nt Elder	2 FEE OF \$57.
FOR WHICH PERMISSION IS GRANTED	<u> </u>	
то тар	SEWER ON THE	
of <u>CADINO</u> V)658	AVE. ST. TYPE OF STREET	
THE PREMISES BEING LOT NO. 150.3	3 House	NO. 2340
WORK TO BE DONE IN ACCORDANCE WITH	Section 29 DULY PAS	SSED BY THE CITY COUNCIL, AND
NAME OF CONTRACTOR	6 Bu	6 mynt Buld
NAME OF CONTRACTOR	<u>'a 1 C X C</u>	- (Spec); t
37 1 TO 1		Iding only Any work

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.