$N^{\underline{0}}$ 10466

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 6/28/95	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM			
HOUSE NO. 2300 SIZE OF PIPE USED 6 plastic	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH			
WAS LATERAL AT CURB? 165	NAME OF CONTRACTOR BON-1000			
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.				
√ N	7,5d			
1 Cmc.	Cyprus SE			
Inspector for City	L STATE STATE STATE STATE STATES STAT			
REMARKS				

Jues am

№ 10466

OFFICE OF THE DIRECTOR OF PUBLIC SEI PERMIT TO TAP SEWER

	MAS	SILLON, OHIO,	<u> </u>
RECEIVED OF	Belowert	<i>i</i>	
FOR WHICH PERMISSION IS GRAN			
то тар			
or(4111112 1/12		·	
THE PREMISES BEING LOT NO			
WORK TO BE DONE IN ACCORDAN	ice with Section 29 service. Codified Ordina	DULY PASSED BY THE	CITY COUNCIL, AND
NAME OF CONTRACTOR	Transport Car	P.	OBON 4 AH WU.
Note: This perm	it covers work out	ide of building onl	y. Any work

walls of building is subject to Massillon Board of Health Regulations.