

Nº 10470

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR  
AND SIGNED WHEN RETURNED

DATE INSPECTED \_\_\_\_\_

IF SO HOW AND LOCATION FROM  
FIRST MANHOLE DOWN STREAM \_\_\_\_\_

HOUSE NO. 1519 \_\_\_\_\_

DISTANCE FROM FIRST MANHOLE  
DOWN STREAM TO DITCH AT  
CURB LINE AND DEPTH \_\_\_\_\_

SIZE OF PIPE USED \_\_\_\_\_

WAS LATERAL AT CURB? \_\_\_\_\_

WAS ATTACHED TO MAIN \_\_\_\_\_

NAME OF CONTRACTOR

H & W contractors

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

cutoff was performed with no inspection

7/12/95

Engineers office was notified at 11:45am

11:30am

of work being done. I arrived @ 11:52am  
and the contractor had already left.

SIGNED \_\_\_\_\_

John A. McAule  
Inspector for City

FILED AT ENGINEER'S OFFICE \_\_\_\_\_

REMARKS \_\_\_\_\_

cut off  
Nº 10470

OFFICE OF THE DIRECTOR OF PUBLIC SE  
**PERMIT TO TAP SEWER**

MASSILLON, OHIO, June 30

RECEIVED OF H + W FEE OF \$ 15.

FOR WHICH PERMISSION IS GRANTED \_\_\_\_\_

TO TAP cap SEWER ON THE North  
OF 1519 Walnut AVE. TYPE OF STREET Public

THE PREMISES BEING LOT NO. 3839, HOUSE NO. 1519

WORK TO BE DONE IN ACCORDANCE WITH Section 29 DULY PASSED BY THE CITY COUNCIL, AND  
OF THE DEPARTMENT OF PUBLIC SERVICE. Codified Ordinances

NAME OF CONTRACTOR H + W

**Note: This permit covers work outside of building only. Any work  
walls of building is subject to Massillon Board of Health Regulations.**