

N^o 10478

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED _____

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM _____

HOUSE NO. 59

SIZE OF PIPE USED 6"

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH _____

WAS LATERAL AT CURB? _____

WAS ATTACHED TO MAIN _____

NAME OF CONTRACTOR HADERBARN

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

Not inspected

MAIN RELAYED
10475



#59
PEARL

#55

49

ALMOND

ALLEY

45°

4' N. of curb

45°

48'

SIGNED _____

[Signature]
Inspector for City

FILED AT ENGINEER'S OFFICE _____

REMARKS _____

replace
Nº 10478

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

MASSILLON, OHIO, *July 23*

RECEIVED OF *Holdenbaum*

FEE OF \$ *50*

FOR WHICH PERMISSION IS GRANTED *WATER*

TO TAP *replace sewer*

SEWER ON THE

OF *Pearl Ave SE*

AVE.

ST. TYPE OF STREET

THE PREMISES BEING LOT NO. *388.5*

HOUSE NO. *59*

WORK TO BE DONE IN ACCORDANCE WITH
OF THE DEPARTMENT OF PUBLIC SERVICE.

Section 29
Codified Ordinances

DULY PASSED BY THE CITY COUNCIL, AND

NAME OF CONTRACTOR *Holdenbaum*

**Note: This permit covers work outside of building only. Any work
walls of building is subject to Massillon Board of Health Regulations.**