

Nº 10509

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 2/13/96

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

HOUSE NO. 1731-1133

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

SIZE OF PIPE USED

WAS LATERAL AT CURB?

WAS ATTACHED TO MAIN

NAME OF CONTRACTOR

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

*Info. in demo file in
BUILDING DEPARTMENT*

SIGNED

C. M. W.
Inspector for City

FILED AT ENGINEER'S OFFICE

REMARKS

cut off - plug toilet caps on 2/13/96

Cut off
Nº 10509

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

MASSILLON, OHIO, *July 13*

RECEIVED OF *Bottill & Co*

FEE OF \$ *15*

FOR WHICH PERMISSION IS GRANTED *under*

TO TAP *under*

SEWER ON THE

OF *Huron Rd SE*

AVE.
ST.

TYPE OF STREET

THE PREMISES BEING LOT NO. *12625*

, HOUSE NO. *1731-173*

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19-1971 DULY PASSED BY THE CITY COUNCIL, AND
OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR *Bottill & Co*

*Phyllis
Robinson
duplex*

**Note: This permit covers work outside of building only. Any work
walls of building is subject to Massillon Board of Health Regulations.**