Nº 10511 FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

| DATE INSPECTED 2-26-96 | IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM 12.3 | |
|---|---|--|
| HOUSE NO. 1308 | | |
| SIZE OF PIPE USED | DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH | |
| WAS LATERAL AT CURB? 165 | 1-PL | |
| WAS ATTACHED TO MAIN YOU S | NAME OF CONTRACTOR | |
| SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED. | | |
| | 2'06 P 90° Q' P | |
| SIGNED BILL Pappus | 116 PET STEP AT ENGINEER'S OFFICE | |
| Inspector for City | | |
| | | |

\frac{1}{\sigma_r} \rightarrow \frac{1}{\sigma_r} \rightarrow

OFFICE OF THE DIRECTOR OF PUBLIC SEI PERMIT TO TAP SEWER

| | MASSILLON, OHIO FEBRUSO | |
|--|---|--|
| RECEIVED OF | Phas ExxCAVATINENOF 558 | |
| FOR WHICH PERMISSION IS GRAN | TED | |
| TO TAP | SEWER ON THE | |
| DF 11 /11 (110 | AVE. ST. TYPE OF STREET | |
| THE PREMISES BEING LOT NO | 15090 , HOUSE NO. 1308 | |
| WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19-1971 DULY PASSED BY THE CITY COUNCIL, AND OF THE DEPARTMENT OF PUBLIC SERVICE. | | |
| NAME OF CONTRACTOR | Dave Pap. | |
| | it covers work outside of building only. Any work | |

walls of building is subject to Massillon Board of Health Regulations.