Nº 10532

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

| DATE INSPECTED 6-10-96 | IF SO HOW AND LOCATION FROM 37' |
|--|---|
| HOUSE NO. 1685 | |
| SIZE OF PIPE USED | DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH |
| WAS LATERAL AT CURB? YES | |
| | NAME OF CONTRACTOR LISSON Eyec |
| WAS ATTACHED TO MAIN JES | NAME OF CONTRACTOR SUSSOI THE |
| SHOW BY DIAGRAM RELATION OF LATERAL TO WAL | L OF BUILDING SERVED. |
| | 31' 7 564"Pipe 7'DEEP |
| SIGNED Bill assay | FILED AT ENGINEER'S OFFICE |

TAP

Nº 10532

OFFICE OF THE DIRECTOR OF PUBLIC SEI PERMIT TO TAP SEWER

| | MASSILLON, | оню. | | 10 | |
|--|--------------|----------|-------|----------------|---------------------------------------|
| RECEIVED OF Dennis | 7))ch | L | | FEE OF \$ | 51 |
| FOR WHICH PERMISSION IS GRANTED | | <u> </u> | | | |
| ro táp | SEWER ON THE | <u> </u> | Litel | 5 / | · · · · · · · · · · · · · · · · · · · |
| of Killy Mt 511 | AVE. | r | : | | |
| THE PREMISES BEING LOT NO. | | | | | |
| WORK TO BE DONE IN ACCORDANCE WITH ORDIN DF THE DEPARTMENT OF PUBLIC SERVICE. | | M/m v | Denni | 5 M | |
| NAME OF CONTRACTOR | E/E | <i>i</i> | 10 | n.+ | |

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.