N^{0} 10550

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 12-12-96	IF SO HOW AND LOCATION FROM 275
HOUSE NO. 1628	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT
WAS LATERAL AT CURB? 1/2	CURB LINE AND DEPTH
WAS ATTACHED TO MAIN 155 SHOW BY DIAGRAM RELATION OF LATERAL TO WAL	NAME OF CONTRACTOR Malaute Eye, L OF BUILDING SERVED.
en e	3' 4 60' 0'2507
	6'DETP 8'DETT
SIGNED BELL CONTROL Inspector for City	FILED AT ENGINEER'S OFFICE
REMARKS	

Nº 10550

OFFICE OF THE DIRECTOR OF PUBLIC SEI PERMIT TO TAP SEWER

	MASSILLON, OHIO,
RECEIVED OF WATER	Lie ve laprient or . E
FOR WHICH PERMISSION IS GRANTED	V
TO TAP AAN LUAY SE	EWER ON THE 1011
OF CAVE. T	YPE OF STREET A C D
THE PREMISES BEING LOT NO. 6436	, HOUSE NO. 1626
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE N OF THE DEPARTMENT OF PUBLIC SERVICE.	IO. 19-1971 DULY PASSED BY THE CITY COUNCIL, AND
NAME OF CONTRACTOR) 1 4 6 4 14 7	Exica (1)

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.