Nº 10563

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

| DATE INSPECTED 9-6-96 | IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM | |
|---|--|--|
| HOUSE NO | , | |
| SIZE OF PIPE USED | DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH | |
| WAS LATERAL AT CURB? VES | CORB LINE AND DEFIN | |
| WAS ATTACHED TO MAIN_ 7E5 | NAME OF CONTRACTOR Holderstown | |
| SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED. | | |
| SIGNED Bill Passus | 17 2205'6" DEFF 17 2205'6" DEFF 39' Existing Lot P'N 58' FILED AT ENGINEER'S OFFICE | |
| Inspector for City | | |
| DEMARKS | | |

Nº 10563

OFFICE OF THE DIRECTOR OF PUBLIC SEI PERMIT TO TAP SEWER

| | , MASSILLON, OHIO, 1114 26 |
|---|--|
| RECEIVED OF | MASSILLON, OHIO, 1115 CAS |
| OR WHICH PERMISSION IS GRANTED | i. |
| o tàp | SEWER ON THE |
| FJ. AVE | TYPE OF STREET (LC.5 L7.C.6.1) |
| HE PREMISES BEING LOT NOPE 1496 PL | 497 + 1483 HOUSE NO. 1111 |
| YORK TO BE DONE IN ACCORDANCE WITH ORDINANC OF THE DEPARTMENT OF PUBLIC SERVICE. | E NO. 19-1971 DULY PASSED BY THE CITY COUNCIL, AND |
| IAME OF CONTRACTOR HALL CULTURE | 201 |
| | |

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.