

Nº 10571

**FOLLOWING DATA TO BE ANSWERED BY INSPECTOR  
AND SIGNED WHEN RETURNED**

DATE INSPECTED \_\_\_\_\_ IF SO HOW AND LOCATION FROM  
FIRST MANHOLE DOWN STREAM \_\_\_\_\_

HOUSE NO. \_\_\_\_\_

SIZE OF PIPE USED \_\_\_\_\_ DISTANCE FROM FIRST MANHOLE  
DOWN STREAM TO DITCH AT  
CURB LINE AND DEPTH \_\_\_\_\_

WAS LATERAL AT CURB? \_\_\_\_\_

WAS ATTACHED TO MAIN \_\_\_\_\_ NAME OF CONTRACTOR \_\_\_\_\_

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

No Inspection Records

SIGNED \_\_\_\_\_ FILED AT ENGINEER'S OFFICE \_\_\_\_\_  
Inspector for City

REMARKS \_\_\_\_\_

SW

Nº



OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

## PERMIT TO TAP SEWER

MASSILLON, OHIO,

Sept 9, 1996

RECEIVED OF

MDS Development

FEE OF \$

50.00

FOR WHICH PERMISSION IS GRANTED

same

TO TAP

san

SEWER ON THE

north

SIDE

OF

Shaw Ave NE

AVE.

ST. TYPE OF STREET

res

THE PREMISES BEING LOT NO.

13950

HOUSE NO.

404

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19-1971 DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

Malavite

owner

no units

(1)

Note: This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health Regulations.